









C40 PRO

HIGH PERFORMANCE CPU COOLER





EN- Please read these instructions before installation.
ES- Por favor lea estas instrucciones antes de la instalación.
PT- Por favor, leia estas instruções antes da instalação.
FR- Veuillez lire ces instructions avant l'installation.
IT- Si prega di leggere queste istruzioni prima dell'installazione.
DE- Bitte lesen Sie diese Anweisungen vor der Installation.

AMD: AM5 / AM4 / AM3




AMD: AM5 / AM4 / AM3




EN- Apply thermal paste to the surface of the CPU.
ES- Aplicar pasta térmica en la superficie de la CPU.
PT- Aplique pasta térmica na superfície da CPU.
FR- Appliquez de la pâte thermique sur la surface du processeur (CPU).
IT- Applicare la pasta termica sulla superficie della CPU.
DE- Tragen Sie Wärmeleitpaste auf die Oberfläche der CPU auf.

AMD: AM5 / AM4 / AM3




EN- Remove the protective film.
ES- Retire la lámina protectora.
PT- Remova a película protetora.
FR- Retirez le film protecteur.
IT- Rimuovere la pellicola protettiva.
DE- Entfernen Sie die Schutzfolie.




EN- Install the AMD brackets.
ES- Instalación de los soportes AMD.
PT- Instale os suportes AMD.
FR- Installez les supports AMD.
IT- Installare i supporti AMD.
DE- Installieren Sie die AMD-Halterungen.

AMD: AM5 / AM4 / AM3



EN- Install the heat sink.
ES- Instalación del disipador de calor.
PT- Instale o dissipador de calor.
FR- Connectez les ventilateurs au câble OPT, puis à la prise du ventilateur du processeur sur la carte mère.
IT- Collegare le ventole al cavo OPT e successivamente al connettore della ventola della CPU sulla scheda madre.
DE- Schließen Sie die Lüfter an das OPT-Kabel an und dann an den CPU-Lüfteranschluss auf der Hauptplatine.



EN- Airflow direction.
ES- Dirección salida de aire.
PT- Direção do fluxo de ar.
FR- Direction du flux d'air.
IT- Direzione del flusso d'aria.
DE- Luftstromrichtung.








C40 PRO


HIGH PERFORMANCE CPU COOLER

www.hiditec.com


INTEL: 1851 /1700 /1366 /1200 /LGA 115X



INTEL: 1851 /1700 /1366 /1200 /LGA 115X




EN- Remove the protective film.
ES- Retire la lámina protectora.
PT- Remova a película protetora.
FR- Retirez le film protecteur.
IT- Rimuovere la pellicola protettiva.
DE- Entfernen Sie die Schutzfolie.




EN- Install the Intel backplate.
ES- Instalación placa trasera de Intel.
PT- Instale a placa traseira Intel.
FR- Installez la plaque arrière Intel.
IT- Installare la piastra posteriore Intel.
DE- Installieren Sie die Intel-Rückplatte.

INTEL: 1851 /1700 /1366 /1200 /LGA 115X




EN- Install the Intel brackets.
ES- Instalación de los soportes de Intel.
PT- Instale os suportes Intel.
FR- Installez les supports Intel.
IT- Installare i supporti Intel.
DE- Installieren Sie die Intel-Halterungen.




EN- Apply thermal paste to the surface of the CPU.
ES- Aplicar pasta térmica en la superficie de la CPU.
PT- Aplique pasta térmica na superfície da CPU.
FR- Appliquez de la pâte thermique sur la surface du processeur (CPU).
IT- Applicare la pasta termica sulla superficie della CPU.
DE- Tragen Sie Wärmeleitpaste auf die Oberfläche der CPU auf.

INTEL: 1851 /1700 /1366 /1200 /LGA 115X





EN- Install the heat sink.
ES- Instalación del disipador de calor.
PT- Instale o dissipador de calor.
FR- Installez le dissipateur thermique.
IT- Installare il dissipatore di calore.
DE- Installieren Sie den Kühlkörper.



EN- Airflow direction.
ES- Dirección salida de aire.
PT- Direção do fluxo de ar.
FR- Direction du flux d'air.
IT- Direzione del flusso d'aria.
DE- Luftstromrichtung.

7

EN- Connect the fans to the OPT cable and then to the CPU fan socket on the motherboard.
ES- Conecte los ventiladores al cable OPT y éste al zócalo del ventilador de la CPU en la placa base.
PT- Conecte os ventiladores ao cabo OPT e, em seguida, ao conector do ventilador da CPU na placa-mãe.
FR- Connectez les ventilateurs au câble OPT, puis à la prise du ventilateur du processeur sur la carte mère.
IT- Collegare le ventole al cavo OPT e successivamente al connettore della ventola della CPU sulla scheda madre.
DE- Schließen Sie die Lüfter an das OPT-Kabel an und dann an den CPU-Lüfteranschluss auf der Hauptplatine.



TDP:	290W
Intel Platform:	Intel: 1851/1700/1366 /1200/115x
AMD Platform:	AMD: AM5/AM4/AM3
Product Size:	143*146*164.5mm
Radiator:	Dual Radiator with black coating
Fan Bearing:	FDB Bearing
Fan Size:	140*140*25mm
Fan Quantity:	2PCS
Fan Speed:	800-1800RPM ±10%
Fan Noise:	29.6DB(A)
Fan Airflow:	95.5CFM
Fan Air Pressure:	2.25MM H2O
Fan Connector:	PWM 4 PIN
Fan Working Voltage:	12V
Fan Working Life:	50000 Hours

EN- Before installing the C40PRO, remove the fans, secure the heat sink, and reinstall the fans.
ES- Antes de instalar el C40PRO, retire los ventiladores, asegure el disipador y vuelva a instalar los ventiladores.
PT- Antes de instalar o C40PRO, remova os ventiladores, fixe o dissipador e reinstale os ventiladores.
FR- Avant d'installer le C40PRO, retirez les ventilateurs, fixez le dissipateur thermique et réinstallez les ventilateurs.
IT- Prima di installare il C40PRO, rimuovere le ventole, fissare il dissipatore di calore e reinstallare le ventole.
DE- Vor der Installation des C40PRO entfernen Sie die Lüfter, sichern Sie den Kühlkörper und installieren Sie die Lüfter erneut.