

ATTENTION!!!

Handle with care during installation.

Any accidental damage to the paint coating during installation may lead to rust formation.

● **Product Basic Description**

This metal container is manufactured from galvanized steel and finished with a protective paint coating.

The protective zinc coating at corners and folded areas has lower strength than that on smooth flat surfaces. Any damage to the paint film during installation will compromise long-term durability and cause premature rusting.

● **Immediate Damage Repair Guideline**

If the paint coating is accidentally damaged, we recommend immediately restoring the surface with the dedicated RAL 9016 acrylic paint, carefully covering all exposed bare metal areas.

● **Post-Installation Rust Remediation Procedure**

If rust is discovered long after installation, caused by previously undetected paint coating damage, please follow these steps in sequence:

1. clean the affected area to completely remove all existing rust deposits.
2. Apply a professional rust converter product to the treated surface.
3. Perform final touch-up finishing on the repaired area using RAL 9016 paint.